

## **Manufacturing Division**

### **Technology Committee**

October 19, 2016









#### **Our Participants**

- Jesse Bonfeld
- Bob Erickson
- Kevin Fischer
- Mike Lemon
- Justin Rothwell











### **Agenda**

- JDMTP AME Taxonomy Alignment and Portfolio Review capability
  - Review Taxonomy construction and definitions of AME taxonomy
  - Provide comment and feedback on coverage and organization
  - Identify manufacturing technology gaps that need to be overcome in order to enable ManTech "joint pursuits"
  - Discuss opportunities to share the message

How can DMSMS community collaborate with Technology committee on improving awareness and promoting greater application of technology advances for more cost effective resolution of DMSMS issues?

- DMSMS Commonality Assessment
  - What are the technologies to consider?
- How can industry be incentivized to be more proactive?











## **JDMTP AME Project**



#### Portfolio Comparison Initial Objectives



- Identify Gaps, Trends and Opportunities
- Define Methods to Understand and Document:
  - Similarities Between Projects in the AME Portfolio
  - Relationship of Projects to Various Thrust Areas
- ✓ Prototype Visualization of Results
  - Verify Methodology with Stakeholders
  - Provide Recommendations for Systemization

During Portfolio Reviews, it is apparent many projects are addressing similar issues and fall within one or more of the same thrust areas. While individual projects are so documented, the aggregate relationships are not so easy to visualize and understand




#### **JDMTP AME Taxonomy**



#### **AME Subpanel Taxonomy**



AME is a set of robust Manufacturing Strategies & Integrated Capabilities that Enable Productivity Growth and a Highly Connected & Collaborative Enterprise





## Compare and Associate Projects in MANTECH Portfolio to Technologies and Best Practices



#### AME Portfolio vs. Thrust Areas/Technologies



Group Identified Strong, Med, Weak Relationships

																																				_
Projects ===	_		Þ						with CVM Plen A Day		- 10						ion al Techniques	package Benelope					Actionable	diseases as				- Bunn		t poor p	armellerite	o Application	Angeroaked 10			
AME Thrust Areas Key Enabling Technology	::	-36 As combit blets data biografice	School of Packey Workload Planning	Smarthbarn Steining Schiller	300 0000	Rech hins Anna this	GMENIOR	CS Critical Researce Plansing	protrosting historial copietos will CA	Spannik Change detarrences	Adhiotice for Se 45ka pe Pro e	Before Check Greek	(Titoesect	000 Oglat Soyboarding	star Cuitting Packaged Units	oby Planning Antoniation	Trade Price of Localing Dimensional To	Oblightblandchring! Work-packs		Align	UTABILITY occurs (MO)	UTABBID Processes (Rallee@Wm)	celecidate Capters for Real Three	ck Abbillods Betton-Contactbles	ensettlate Asabitos CRADA	authorizing Process Drives Design	rity beleate	concensional Replication Sychemistalist	amessWorks	Compating for blanch charles Housings	hiệ ở Sautabroei Asabata tha connociti	ropiddy a cedinously aj by ug sagmesjey paci	Nei-Office Digital Work Instructions A Angeronia	UTAMBUR Chippy Chair	(Lithtersperability)	
Domains		ž	å	ě	1	Hos	Ē	MOSO	å	å	CADIC	8	Ě	900	ž	Capacity	ž.	ä	ASPAR	Anna,	ŧ	#10	į	ĕ	ě	i	å	i	į	1	Hand.	Advanced	2	ŧ	ž	
Domains		_					•		_	٠	9	Ξ	2	2	2	2	2	ь	4	2	8	ä	#	4	ā	#	8	ā	12	8	9	=	2	2	4	
Connecthe Energrise	1	$\diamond$	$\infty$	Ŏ.	X	$\Diamond$	X	O.	X	Ŏ.	X	X	×	OX.	$\otimes$	X	X	ĊX.	X		X	X	X	X	$\diamond$	X	Ø	X	Ó	$\propto$	Ø	X	$\otimes$	$\propto$	$\diamond$	
NGE (Connected Systems)	2	•		٠	•	•	•	П		٠	٠			•				٠	•				٠	•	•	٠	٠			•				•	•	
Data and Taxonomy Standards	2	Г					•	П	П				•	•													٠								•	
Data (Integration; Interogerability and Shart	n pë	•	•	٠	•	4	•	•	•	٠	•	٠	•			•	٠	۰	•		٠	•	٠	٠		•	•		•	۰					٠	
IT Framework			•					•		4		•				•																			•	
ôdvanced ônalytics	•	L						•	۰																٠		•									
Build the Digital Thread	7	X	X	X	ČΧ	X	Ŏ4	X	Ճ	X	ČΧ	X	ČΧ	X	X	X	ČΧ	X	X		X	X	X	Ŏ	X	Ŏ	$\propto$	Ŏ	$^{\circ}$	Ŏ	X	Ŏ	X	×	$\times$	
Max (Detailed Needs)	•	٠		٠		•	٠							٠					•		٠	٠	٠	٠		•	٠		•	Ш			•	٠	٠	
Supply Chain and Logistics		L						0	0												Ð	٠	٠	٠	٠		٠				٠			•		
Operations & Maintenance (Sustainability)	10	匚	٠		٠			$\Box$	$\Box$												•	•	٠	٠	•		-	•		Ш	•	٠	•	•	Ш	
Model Re-Use	11	匚	$oxed{oxed}$				$\Box$	$\dashv$	$\Box$		•			•			0									•	•			Ш		٠	4	•	Ш	
Design-Manufacturing Interesion	12	L		Ш	Ш								L.	L.	•	L	L.	L			4	•		L		•			•	Ш		L.	4	4	4	
Create an áglis Factory Floor	19	X	XX	X	X	$\propto$	$\propto$	X	$\propto$	X	88	X	X	$\propto$	Ø	$\propto$	×	X	XX		X	X	X	X	X	X	X	X	×	$\propto$	X	•	X	X	ŏ	
Intelligent Factory	14	乚	$oxed{oxed}$	۰	Ш	Щ	_	_	_				٠	$ldsymbol{ld}}}}}}$	$ldsymbol{le}}}}}}$		۰						•	٠	Ш			٠	•	Ш	€	٠	•		Ш	
Machine dnalytics	15	ᆫ	┖	Ш	Ш	Щ	_	_	_				$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$		$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$	_				٠			Ш					Ш		٠	Ш	Ш	Ш	
ådagdve Manufacturing	16	⋄	$oxed{oxed}$	Ш	Щ	Щ	_	_	_				Щ	Щ	Ш	$ldsymbol{ldsymbol{ldsymbol{eta}}}$	Щ	_	Ш		Ш		٠	•	Ш		Ш	•	•	Ш		٠	Ш	Ш	Ш	
Rapid Response	17	ᆫ	$oxed{oxed}$	0	Ш	Щ	_	_	_				$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$			$ldsymbol{ldsymbol{ldsymbol{eta}}}$		Ш			-	٠	•	Ш			•	•	Ш	٠	٠	Ш	Ш	Ш	
Production Planning and Scheduling	18	ᆫ	۰	Ш	Щ	Щ	_	•	٠	٠		٠	Ш	Ш	٠	۰	Ш	_	Ш		٠	٠	٠	$\vdash$	Ш		Ш		Ш	ø	٠		٠	Ш	Ш	
Model-Based Manufacturing	19	L	L.	Щ	۰	Ш	_	_	_	_	0	_	L.	L	L.	L.	L.	L.			Ц	٠	_	٠		٠	Ц	٠	٠	Ш	٠	٠	Ш		Ц	
Ensure a Robustinflastructure	20	$\propto$	$\otimes$	$\sim$	$\propto$	$\propto$	$\propto$	$\sim$	X	X	QX	X	$\propto$	$\otimes$	$\propto$	$\otimes$	X	$\otimes$	$\propto$		X	X	X	Ŷ	$\propto$	$\Diamond$	$\propto$	Q	$\propto$	$\Diamond$	X	Q	٠	$\sim$	$\times$	
Cyber Security	21	匚	$oxed{oxed}$	Ш	Ш	Ш	_	_	_				$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$		$ldsymbol{ldsymbol{ldsymbol{eta}}}$				Ш			L	Ш		$\sqcup$		Ш	Ш			Ш	Ш	Ш	
Work Force Education and Training	22	∟	•	Ш	Ш	•	_	_	_				$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$ldsymbol{ldsymbol{ldsymbol{eta}}}$	$oxed{oxed}$	lacksquare	0	0	Ш		Ш			L					Ш	•		•	•		Ш	
Risk dnalysis	22	∟	$\vdash$	Щ	Щ	Щ	_	_	_	Ц			lacksquare				$ldsymbol{ldsymbol{ldsymbol{eta}}}$							L	•	0	•			0	۰	_	Ш	₽	Ш	
Business Processes	24	ᆫ										٥		ø		ø			0		0	٠								٠	0		Ш		Ш	



# **Back-up Slides**









### Participants (name, org, email)

Name	Organization	Email Address
Jesse Bonfeld	Next Level Solutions	jmbonfeld@gmail.com
Bob Erickson	Raytheon	rderickson@raytheon.com
Kevin Fischer	Rockwell Collins	kevin.fischer@rockwellcollins.com
Mike Lemon	ITI	mike_l@iti-global.com
Justin Rothwell	ProAxion	justin@proaxion.io





